

# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

## Inspection Report Minerals Regulatory Program

June 24, 2005

Supervisor	DRA
------------	-----

Mine Name: Brown Sandstone Operator Name: Feller Stone, Inc. **Permit number:** S/053/019 **Inspection Date:** June 21, 2005

Time:

Inspector(s): Doug Jensen

Other Participants: Russ Feller-Feller Stone, Inc.

Mine Status: Inactive

Weather: Hot, Cloudy

<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages			
4. Explosives, magazines			
5. Deleterious Material			
6. Roads (maintenance, surfacing, dust control, safety)			
7. Concurrent Reclamation			
8. Erosion Control			
9. Demolition			
10.Backfilling/Grading (trenches, pits, roads,			
highwalls, shafts, drill holes)			
11. Water Impoundments			
12. Soils			
13. Revegetation			
14. Air Quality			
15. Other: Inspect & Close	X	X	

#### **Purpose of Inspection:**

Permitee requested that the Division inspect and close this permit.

### **Inspection Summary:**

16. The site is located across the river near a gravel quarry operated by SunRoc. This site is similar to the Cobble/Sandstone permit that we visited earlier in the day as the rock harvested was material that was on the surface.

It has been several years since Feller Stone had removed any rock for this area and any impacts that their mining activity had created was not evident.



Inspection Date: June 21, 2005; Report Date: June 24, 2005

Page 2 of 2 S/053/019

> There are no long term impacts caused by mining at the site. No pits or excavations were evident. The vegetation in the areas where rock removal had taken place had recovered and vegetation in these areas was as good as the surrounding areas.

#### **Conclusions and Recommendations:**

This site can be released.

Inspector's Signature Laburg

Date: \_\_\_\_ June 24, 2005

Dj:jb

cc: Feller Stone, Inc., Operator

John Blake, SITLA

Attachment: Photos

O:\M053-Washington\S0530019-BrownSandstone\Inspections\06212005insp.doc

